

State of California - The Resources Agency  
DEPARTMENT OF PARKS AND RECREATION  
PRIMARY RECORD

Primary # 30-158719  
HRI # 038085  
Trinomial ORA  
NRHP Status Code 5D1

Other Listings:

Review Code:

Reviewer:

Date:

Page 1 of 3

\*Resource Name or #:  
(Assigned by Recorder)

CLARK\_S\_133\_\_APN\_390-672-06

P1. Other Identifier:

\*P2. Location:

☐ Not for Publication

☒ Unrestricted

\*a. County:

Orange

and (P2b and P2c or P2d. Attach a location map as necessary.)

\*b. USGS 7.5' Quad:

Date:

T

R

1/4 of

1/4 of

Sec

B.M.

c. Address:

133

-

S CLARK

ST

, #

City:

Orange

Zip:

92868

d. UTM: (Give more than one for large and/or linear resources)

Zone

'

mE/

mN

e. Other Locational Data:

\*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries. Continues on Pg.3.)

Materials:

Frame - Wood siding

Box plan with pyramid roof. Front portion of roof extends to form porch overhang and is supported by wood posts. Angled bay window on front facade rises up through main roof and is topped by a conical roof itself. Windows are high, vertical, double-hung windows. Some modifications have been made to the house, including addition of dormer on side, new siding, and lattice work connecting porch posts.

\*P3b. Resource Attributes: (HP2)--Single family property  
(List attributes and codes)

\*P4. Resources Present:

☒ Building

☐ Structure

☐ Object

☐ Site

☒ Element of District

☐ District

☐ Other (Isolates, etc.)



P5b. Description of Photo:

2005

(View, date, accession #)

\*P6. Date Constructed/ Age and Source:

1917

☒ Historic

☐ Prehistoric

☐ Both

\*P7. Owner and Address:

\*P8: Recorded by: (Name, affiliation, and address)

D. Gest, P. LaValley, D.  
Matsumoto

Chattel Architecture

13417 Ventura Blvd.

Sherman Oaks, CA 91423

\*P9. Date Recorded:

March, 2005

\*P10. Survey Type: (Describe)

Reconnaissance

\*P11. Report Citation:

(Cite survey report and other sources, or enter "none.")

Orange County Assessor Records (2005). Chattel Architecture (2005)  
Historic Resources Survey. AEGIS (1991) Historic Building Inventory  
Update. Heritage Orange County, Inc. (1982) Orange Historic Survey.

\*Attachments:

☐ NONE

☐ Location Map

☒ Continuation Sheet(s)

☒ Building, Structure, and Object Record

☐ Archaeological Record

☐ District Record

☐ Linear Feature Record

☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record

☐ Photograph Record

☐ Other (List):

DPR 523A (1/95)

\*Required Information

State of California - The Resources Agency  
DEPARTMENT OF PARKS AND RECREATION  
BUILDING, STRUCTURE, AND OBJECT RECORD

Primary # 30-158719  
HRI # 038085  
\*NRHP Status Code 5D1

Page 2 of 3

\*Resource Name or #: CLARK\_S\_133\_\_APN\_390-672-06  
(Assigned by Recorder)

B1. Historic Name: Unknown

B2. Common Name:

B3. Original Use: RES B4. Present Use: RES

\*B5. Architectural Style: Hip Roof Cottage

\*B6. Construction History: (Construction date, alterations, and date of alterations) Date of Construction: 1917 ☒ Historic ☐ Prehistoric ☐ Both

Some modifications have been made to the house, including addition of dormer on side, new siding, and lattice work connecting porch posts. Since the 1982 survey, this structure has been altered with appropriate removal of inappropriate siding and lattice work.

\*B7. Moved? ☒ No ☐ Yes ☐ Unknown Date: Original Location:

\*B8. Related Features:

\*B9. Architect or Builder: Unknown

\*B10. Significance: Theme: Architecture Area: City of Orange Property Type: Residence

Period of Significance: Old Towne: Early Settlement (c. 1870 - 1920) Applicable Criteria: AC

(Discuss importance in terms of historical or architectural context as defined by theme, period, and geographic scope. Also address integrity. Continues on Pg.4.)

Structural Integrity: Fair Condition - Minor and reversible or appropriate changes to original structure.

Site Integrity: Accessory structure or major addition and other inappropriate changes that compromises the scale or association with the site.

Opportunities:

B11. Additional Resource Attributes: (List attributes and codes)

\*B12. References:

Orange Daily News.

B13. Remarks: (Continues on Pg.3.)

Status change since 1991 Survey: None.

(Sketch Map with North arrow required.)

\*B14. Evaluator: Robert Chattel

\*Date of Evaluation: September, 2005

(This space reserved for official comments.)

State of California - The Resources Agency  
DEPARTMENT OF PARKS AND RECREATION  
CONTINUATION SHEET

Primary # 30-158719  
HRI # 038085  
Trinomial ORA

Page 3 of 3

\*Resource Name or #:  
(Assigned by Recorder)

CLARK\_S\_133\_\_APN\_390-672-06

Recorded by:

D. Gest, P. LaValley, D. Matsumoto  
Chattel Architecture  
13417 Ventura Blvd.  
Sherman Oaks, CA 91423

Date Recorded: March, 2005

☒ Continuation ☐ Update

Years Surveyed: 1982, 1991, 2005

Description of Photo: 1991

Listed in National Register:

General Plan:	LDR	# of Buildings:	1
Planning Zone:	R-3	# of Stories:	1
Lot Acre:	0.159	# of Units:	1
Principal Building Sqft:	1071		

B6. Construction History (Continued from Pg.2):

B13. Remarks (Continued from Pg.2):

P3a. Description (Continued from Pg.1):

