State of California - The Resources Agency DEPARTMENT OF PARKS AND RECREATION PRIMARY RECORD Other Listings Review Code:	s:	Primary # HRI # Trinomial NRHP Status Code Reviewer:	111508 ORA 6Z Date:		
	ce Name or #: gned by Recorder)	CHAPMAN_E_924A	PN_390-451-02		
P1. Other Identifier:					
<b>2. Location:</b> Not for Publication	<ul> <li>Unrestricte</li> </ul>	d			
*a. County: Orange	and (P2b and P	2c or P2d. Attach a location map a	is necessary.)		
*b. USGS 7.5' Quad:	Date:	; R;			
C. Address: 924 - E CHAPMAN		AVE			
<ul> <li>d. UTM: (Give more than one for large and/or linear resource. Other Locational Data:</li> </ul>	urces) Zone	'mE/	mN		
Materials: Frame - Wood siding					
(List attributes and codes) 4. Resources Present:  Building .	Structure 🗌 Obj	ect 🗌 Site ✔ Elemen	nt of District District Other (Isolates, etc.) P5b. Description of Photo: 2005 (View, date, accession #)		
A STATE OF A			*P6. Date Constructed/ Age and Source:		
AN ANALY MANUAL MARKET			1921 c		
			Historic 🗌 Prehistoric 🗌 Both		
			*P7. Owner and Address:		
924			*P8: Recorded by: (Name, affiliation, and address) D. Gest, P. LaValley, D. Matsumoto		
			Chattel Architecture		
		t- T	13417 Ventura Blvd.		
			Sherman Oaks, CA 91423		
11 Papart Citation			*P9. Date Recorded:		
<b>11. Report Citation:</b> (Cite survey report and other so Drange County Assessor Records (2005)		chitecture (2005)	May, 2005		
Historic Resources Survey. AEGIS (19 Jpdate.			* <b>P10. Survey Type:</b> (Describe) Reconnaissance		
Attachments: NONE	Location Map District Record Photograph Reco	Continuation Sheet(			

State of California - DEPARTMENT OF I	PARKS AND RI	ECREATION	Primary # HRI #	111508
BUILDING, STR	UCTURE, A	ND OBJECT RECORD	*NRHP Status Code	6Z
Page 2 of 3		*Resource Name or #: (Assigned by Recorder)	CHAPMAN_E_924AP	PN_390-451-02
B1. Historic Name:	Unknown			
B2. Common Name:				
B3. Original Use:	COM	B4. Present Use:	СОМ	
*B5. Architectural Sty	le: Craftsm	an		
*B6. Construction His	tory: (Construction	date, atlerations, and date of alterations	Date of Construction:	1921 c ✔ Historic Prehistoric Both
Altered as of 20	05: Window	s; Infilled/altered por	ch, and Addition(s)	
* <b>B7. Moved? V</b> No	🗌 Yes 🗌 Ur	nknown Date:	Original Location:	
*B8. Related Features	:			
*B9. Architect or Build	der: Unknown	ı		
*B10. Significance:	Theme: A:	rchitecture Area:	City of Orange Pro	operty Type: Commercial
Period of Significan	ce: Old Towr	ne: Interwar Development	t (c. 1921 - 1941)	Applicable Criteria: N/A
(Discuss importance in terms	s of historical or arch	itectural context as defined by theme, pe	riod, and geographic scope. Also a	address integrity. Continues on Pg.4.)
Structural Integrity:	Good Condi	tion - Major inappropr	iate changes to orig	ginal structure.
	cessory stru te.	ucture or major additio	n that compromises	the scale or association with the
Opportunities:				

B11. Additional Resource Attributes: (List attributes and codes)

## \*B12. References:

Orange Daily News.

B13. Remarks: (Continues on	Pg.3.)	(Sketch Map with North arrow required.)
	1991 Survey: Re-evaluation.	
*B14. Evaluator:	Robert Chattel	
*Date of Evaluation:	September, 2005	
(This space reserved for official comm	nents.)	
DPR 523B (1/95)		*Required Information

State of California - The Resources Agency DEPARTMENT OF PARKS AND RECREATION CONTINUATION SHEET		Primary # HRI # Trinomial	111508 ORA			
Page 3 of 3	:	*Resource Name or a (Assigned by Recorde		CHAPMAN_E_924AP	'N_390-451-02	
Recorded by:						
D. Gest, P. LaValle		sumoto		Date Record	ded: May, 2005	
Chattel Architectu 13417 Ventura Blvd Sherman Oaks, CA	•			✓ Continua	ation 🗌 Update	
Years Surveyed:	1991,	2005		Description of Pho	to: 1991	
Listed in National Register	r: 1997					
General Plan:	NOP	# of Buildings:	1	_		10000
Planning Zone:	O-P	# of Stories:	2			
Lot Acre:	0.1511	# of Units:	1	4 3	* ····································	
Principal Building Sqft:	2224					
B6. Construction History (	Continued f	rom Pg.2):				

B13. Remarks (Continued from Pg.2):

P3a. Description (Continued from Pg.1):