

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # 30-159845
HRI # 039211, 111526
Trinomial ORA
NRHP Status Code 1D

Other Listings: _____

Review Code: _____

Reviewer: _____

Date: _____

Page 1 of 3

*Resource Name or #:
(Assigned by Recorder)

CHAPMAN_W_237__APN_039-173-10

P1. Other Identifier: See B13 Remarks

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Orange and (P2b and P2c or P2d. Attach a location map as necessary.)

*b. USGS 7.5' Quad: _____ Date: _____ T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address: 237 - W CHAPMAN AVE, # _____ City: Orange Zip: 92866

d. UTM: (Give more than one for large and/or linear resources) Zone _____ ' _____ mE/ _____ mN

e. Other Locational Data: _____

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries. Continues on Pg.3.)

Materials: Frame - Metal siding

This structure consists of two projecting bays, each supported by columns. The roof of each of these bays is in the curvilinear style with banding typical of Moderne structures.

*P3b. Resource Attributes: (HP6)--Commercial building
(List attributes and codes)

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☒ Element of District ☐ District ☐ Other (Isolates, etc.)

P5b. Description of Photo: 2005
(View, date, accession #)

*P6. Date Constructed/ Age and Source:

1925

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address:

*P8. Recorded by: (Name, affiliation, and address)
D. Gest, P. LaValley, D.
Matsumoto

Chattel Architecture
13417 Ventura Blvd.
Sherman Oaks, CA 91423

*P9. Date Recorded:

May, 2005

*P10. Survey Type: (Describe)

Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none.")

Orange County Assessor Records (2005). Chattel Architecture (2005)
Historic Resources Survey. AEGIS (1991) Historic Building Inventory
Update. Heritage Orange County, Inc. (1982) Orange Historic Survey.

*Attachments: ☐ NONE ☐ Location Map ☒ Continuation Sheet(s) ☒ Building, Structure, and Object Record
☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photograph Record ☐ Other (List): _____

DPR 523A (1/95)

*Required Information



State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
BUILDING, STRUCTURE, AND OBJECT RECORD

Primary # 30-159845
HRI # 039211, 111526
*NRHP Status Code 1D

Page 2 of 3

*Resource Name or #: CHAPMAN_W_237__APN_039-173-10
(Assigned by Recorder)

B1. Historic Name: Super Service Station

B2. Common Name:

B3. Original Use: COM

B4. Present Use: COM

*B5. Architectural Style: Art Moderne

*B6. Construction History: (Construction date, alterations, and date of alterations) Date of Construction: 1925 ☒ Historic ☐ Prehistoric ☐ Both

*B7. Moved? ☒ No ☐ Yes ☐ Unknown Date: Original Location:

*B8. Related Features:

*B9. Architect or Builder: Unknown

*B10. Significance: Theme: Architecture Area: City of Orange Property Type: Gas station

Period of Significance: Old Towne: Interwar Development (c. 1921 - 1941) Applicable Criteria: AC

(Discuss importance in terms of historical or architectural context as defined by theme, period, and geographic scope. Also address integrity. Continues on Pg.4.)

Structural Integrity: Good Condition - No apparent change to original structure.

Site Integrity:

Opportunities:

What is currently an auto repair shop was originally a small gas station and, in fact, one of the first in Orange. This originally served several businesses, including the Super Service Station and California Tire Credit Service.

B11. Additional Resource Attributes: (List attributes and codes)

*B12. References:

Orange Daily News.

B13. Remarks: (Continues on Pg.3.)

Status change since 1991 Survey: None.

Previously known in 1997 listing as: 235-237 W. Chapman.

(Sketch Map with North arrow required.)

*B14. Evaluator: Robert Chattel

*Date of Evaluation: September, 2005

(This space reserved for official comments.)

DPR 523B (1/95)

*Required Information

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
CONTINUATION SHEET

Primary # 30-159845
HRI # 039211, 111526
Trinomial ORA

Page 3 of 3

*Resource Name or #:
(Assigned by Recorder)

CHAPMAN_W_237__APN_039-173-10

Recorded by:

D. Gest, P. LaValley, D. Matsumoto
Chattel Architecture
13417 Ventura Blvd.
Sherman Oaks, CA 91423

Date Recorded: May, 2005

☒ Continuation ☐ Update

Years Surveyed: 1982, 1991, 2005

Description of Photo: 1991

Listed in National Register: 1997

General Plan: OTMIX-15 # of Buildings: 1

Planning Zone: SP # of Stories: 1

Lot Acre: 0.2544 # of Units: 1

Principal Building Sqft: 1100

B6. Construction History (Continued from Pg.2):

B13. Remarks (Continued from Pg.2):

P3a. Description (Continued from Pg.1):

